



Cessna Citation Encore s/n 560 – 0542

Reg. [REDACTED]

AIRCRAFT USAGE/SPECIFICATIONS

Times/Values Current As Of : 4/16/2010 Air Frame Total Time (AFTT) : 3,248 Landings/Cycles : 2,813

ENGINE INFORMATION

Engine Model:	PW535A		Engine Maintenance Program:	Unknown - Unknown		Engine Management Program:	Unknown		On Condition TBO : No
	Serial Number	Total Time Since New (TTSNEW) Hours	Since Overhaul (SOH/SCOR) Hours	Since Hot Inspection (SHI/SMPI) Hours	Time Between Overhaul (TBO/TBCI) Hours	Total Cycles Since New	Total Cycles Since Overhaul	Total Cycles Since Hot	
Engine 1 (Left) :	DC0007	3,248		757	5,000	2,813			
Engine 2 (Right) :	DC0026	3,248		757	5,000	2,813			
Engine 3 (Left) :									
Engine 4 (Right) :									

AUXILIARY POWER UNIT (APU)

Model:	
Serial #:	
APU Maintenance Plan:	Unknown
Total Time (Hours) Since New:	
Since Overhaul (SOH) Hours:	
Since Hot Inspection (SHI) Hours:	

EQUIPMENT DETAILS

General:	Locking fuel caps, life vests, dual AC outlets, 60 Hz inverter, Esso/Exxon 2380
----------	---------------------------------------------------------------------------------

MAINTENANCE/CERTIFICATIONS

Maintained:	JAR Ops 1
Airframe Maintenance Program:	Unknown
Airframe Maintenance Tracking Program:	CESCOM (Cessna Computerized)
Engine Overhaul By:	
Hot Inspection By:	
Damage History Notes:	
Certifications:	RVSM
Inspection:	RVSM. Phase B & 1 - 4 inspections c/w 03/05/07. Phase 18 inspection c/w 09/07/06. Phase 5 inspection c/w 11/08; due 02/19/12



IMPORTANT FEATURE CODES		
STATUS	CODE	DESCRIPTION
Unk	DAM	Damage History
Unk	EMP	Engine Maintenance Program
Yes	CES	CESCOM (Cessna Computerized Maintenance Tracking Program)
Yes	TAW	Terrain Awareness and Warning System
Yes	TCA	Traffic Collision Avoidance System (TCAS)
Yes	SAT	SATCOM
Yes	CVR	Cockpit Voice Recorder
Yes	833	8.33 channel spacing
Yes	FMI	FM immunity
Yes	RVS	RVSM

INTERIOR DETAILS	
Rating:	9
Done By:	Appearance Group
MM/YYYY:	03/2007
Passengers:	8
Configuration:	Executive
Air Conditioning:	Freon
General:	Tan leather interior
Seating:	Mid-cabin 4-place club seating, dual aft forward-facing seats, single entrance seat, belted lav seat
Carpet:	Forest green carpeting, foldable threshold center-aisle carpet assembly
Refreshment Equipment:	Forward LS refreshment center
Cabinetry:	Veneer cabinetry finish, mid-cabin LS & RS foldout tables
Entertainment Equipment:	AvVisor Plus cabin display system
Accessories:	Magazine rack, special sliding headrests, gold plating
Storage:	Aft cabin storage restraint
Lavatory:	Aft private

EXTERIOR DETAILS	
Rating:	10
Done By:	
MM/YYYY:	02/2009
General:	Matterhorn white w/platinim, fawn lagoon & metallic wine stripes

LEASE INFORMATION			
Type	Term	Expiration Date	Expiration Confirmed
	Unknown		
Notes :			



AVIONICS			
ADF:	Dual Honeywell RNZ-850	Autopilot:	Honeywell Primus 1000 IFCS
Avionics Package:	Honeywell Primus 1000 IFCS / Primus II	Communication Radios:	Dual Honeywell RCZ-833E w/8.33 spacing
CVR:	Fairchild A200S	DME:	Dual Honeywell RNZ-850
EFIS:	Honeywell Primus 1000	FDR:	Honeywell SSFDR
Flight Director:	Honeywell Primus 1000 IFCS	FMS:	Universal UNS-1Csp+ w/dual GPS-500
Hi Frequency:	King KHF-950	Navigation Radios:	Dual Honeywell RNZ-850 w/FM immunity
Radar Altimeter:	Honeywell AA-300	SATCOM:	AirCell ST-3100
Stormscope:	BFGoodrich WX-500	TAWS:	AlliedSignal Mark VII w/windshear & RAAS
TCAS:	Bendix/King TCAS-II w/change 7	Transponder:	Dual Honeywell XS-852B Mode S enhanced
Weather Radar:	Honeywell Primus 880		

COCKPIT DETAILS	
Crew Accessories:	Monorail sunvisors, Jeppesen book rack, AC outlet
General:	AlliedSignal Mark VII EGPWS, 8.33 spacing, FM immunity, AirCell ST-3100 SATCOM, dual Honeywell RNZ-850 air data computers, CMS-400 cockpit checklist system, Artex C406-2 3-frequency ELT
General:	PBS-250 cabin briefer, Universal data transfer unit, dual Honeywell 800 flight display system, cabin temperature indicator, voice-activated intercom w/noise-cancelling headsets & IPOD plug, Garmin GDL-49 satellite
General:	SafeFlight N1 computer